

Ademco Download Panel summary																	
Control Panel	Minimum Keypad	Keypads Addressable	Max Partitions	Has IC	User# of MC	Total Users Codes	# of Log Events	Panel Zones Standard	Total Zones	Reserved Zones	Supports Wireless Zones	Supports X-10	Supports Relays	Supports Scheduling	Macro Speed Key	VIP Phone Module	Known Anomalies See legend below
4140AT	Fixed	No	1	01	02	15	-	9	16	4	-	-	-	-	-	-	Z07
4140DM	Fixed	No	1	01	02	22	-	9	64	8	Yes	-	-	-	-	-	Z07
4140DMP	Fixed	No	1	01	02	70	-	9	64	8	Yes	-	-	-	-	-	Z07.TT
4140DMPT	Alpha	Yes	8	01	Any	98/128	224	9	64	8	Yes	-	-	-	-	-	RF.TT
4140DMPT2	Alpha	Yes	8	01	Any	98/128	224	9	87	8	Yes	8	8	Yes	-	-	RF.TT
Vista-40	Alpha	Yes	2	01	Any	88/70	100	9	64	9	Yes	8	8	-	-	Yes	TT
Vista-50	Alpha	Yes	8	01	Any	98/128	224	9	86	9	Yes	16	16	Yes	-	Yes	TT
Vista-50P	Alpha	Yes	8	01	Any	75 each	224	9	86	9	Yes	16	16	Yes	Yes	Yes	F83.TT
4110	No Aip.	No	1	-	01	4	-	6	6	3	No	-	-	-	-	-	Must always site DL
4110DM	No Aip.	No	1	-	01	4 to 8	-	6	14	3 to 5	Yes	-	-	-	-	-	
4110DL	No Aip.	No	1	-	01	4 to 8	-	6	6	3 to 5	No	-	-	-	-	-	
Vista-10	Alpha	No	1	-	01	4 to 8	-	6	22	5	Yes	-	4	-	-	Yes	
Vista-10SE	Alpha	No	1	01	02	7	-	6	22	5	Yes	-	4	-	-	Yes	Must site DL 1st time
4120EC	No Aip.	No	1	01	02	8	-	8	8	2	No	-	-	-	-	-	
4120DM	Fixed	No	1	01	02	70	-	8	64	9	Yes	-	-	-	-	-	
Vista-20	Fixed	No	2	01	02	16 each	48	8	38	5	Yes	8	4	-	-	Yes	
Vista-20SE	Fixed	No	2	01	02	16 each	48	8	38	5	Yes	8	4	-	-	Yes	
5110DM	Fixed	No	1	-	01	6	-	5	5	8	-	-	-	-	-	-	
5120DM	Fixed	No	1	-	01	8	-	5	5	9	-	-	-	-	-	-	
5140DM	Alpha	Yes	1	01	Any	99	224	9	64	10	-	-	-	-	-	-	TT
Vista-100	Alpha	Yes	8	01	Any	128 each	224	8	87	61	Yes	16	16	Yes	Yes	Yes	F83.TT
Known Flaws																	
Z07	DL could cause Zone 7 to trip																
F83	Field 83 needs 000080 programmed in (to fix daylight savings flaw) <Ver.04																
RF	DL does not always read wireless key info correctly																
TT	Timer Tests, if enabled, anytime programming mode is entered, the initial start day of week is reset.																

Vista Panels

Control	Minimum Keypads	Max	Has Install	User # of	Total Users	# of Log On Board	Total	Reserved	Wireless	Supports	Supports	Supports	Macro	VIP	Known	
Panel	Keypad	Addressable	Partitions	Code	M Code	Codes	Events	Zones	Zones	Zones	X-10	Relays	Scheduling	Key	Module	Anomalies
Vista 10	Alpha	No	1		1	4 to 8		6	22	5	Yes		4		Yes	
Vista 10SE	Alpha	No	1	1	2	7		6	22	5	Yes		4		Yes	Must site DL 1st time
Vista 20	Fixed	No	2	1	2	16 ea	48	8	38	5	Yes	8	4		Yes	
Vista 20SE	Fixed	No	2	1	2	16 ea	48	8	38	5	Yes	8	4		Yes	
Vista 40	Alpha	Yes	2	1	Any	68/70	100	9	64	9	Yes	8	8		Yes	TT
Vista 50	Alpha	Yes	8	1	Any	99/128	224	9	86	9	Yes	16	16	Yes	Yes	TT
Vista 50P	Alpha	Yes	8	1	Any	75 each	224	9	86	9	Yes	16	16	Yes	Yes	F83,TT
Vista 100	Alpha	Yes	8	1	Any	128 ea	224	8	87	61	Yes	16	16	Yes	Yes	F83,TT
F83 -- Field 83 needs 000060 programmed in (to fix daylight savings flaw) <ver. 04																
TT -- Timer Tests, if enabled, anytime program mode is entered, the initial start day of week is reset.																